

Care Instructions

wenaCel® comfortPlus Ergonomic Pillow



Care symbols:



To get the most from your products, please ensure that you follow these important care instructions:

- The pillow cover should be washed at least twice per year to maintain optimal hygiene.
- The pillow cover can be washed at up to 60° Celcius on a gentle cycle.
- We recommend the use of wenaCare® laundry detergent, developed especially for Wenatex products. Wool wash or gentle detergents with no harsh chemicals, optical brighteners or bleach can also be used.
- After washing, the pillow cover can be air-dried in the shade.
Caution: the cover is not suitable for tumble drying.
- The wenaPur® comfort cold foam core should not be washed.

We recommend:

wenaCare® Laundry Detergent
for Bedding

If you have any questions,
feel free to contact us.

1300 858 139
enquiries@wenatex.com.au
www.wenatex.com.au